




Unit - Sample HG – 843

## **Cross traverse unit type PSE 4 BZ with slideway unit type H242/me/200-EE, both CNC-controlled**



### **Cross traverse unit type PSE 4 breit contains**

#### **Spindle unit type BF 3**

Motor:	3 phases norm motor 400Volt / 50Hz P= 7,50 KW
Spindle bearing:	precision spindle bearing, i.D.70 mm
Protection:	labyrinth collar with air protection
Spindle nose:	SK 40 including flange for cross traverse head and coolant through spindle system
Belt system:	teeth power belt, exchangeable
Spindle speed:	at about 2.600 rpm (other speed possible)
Mounting pos.:	horizontal or vertical spindle nose to floor

fixed on this unit:

#### **Cross traverse device type, mechanically**

Force system:	by ballscrew and NC-motor
Axial stroke:	at about 40mm, stepless

fixed on

#### **Slideway unit H242/me/200-EE**

Force system:	by ballscrew and NC-motor
Stroke:	max. 200mm

## **Hagen & Goebel Werkzeugmaschinen GmbH**

Saelzerweg 3 , D – 59494 Soest

Telefon +49 29 21 / 5 90 16 – 0

homepage [www.hagengoebel.com](http://www.hagengoebel.com)

Postbox 1444 , D – 59474 Soest

Telefax +49 29 21 / 5 90 16 – 66

e-mail [kontakt@hagengoebel.de](mailto:kontakt@hagengoebel.de)