



Machine sample HG – 677 Outside tapping machine for bolts or pipes



Parts type: Machine design:	Pipes, bolts or shafts in different dimensions High speed tapping unit type GE-16/2, GE-22/2 or GE42 (depends on the threat dimension and needed power) Main spindle in special design including mechanical modification for automatic outside tapping heads Fast retract system for minimum retracting time
	Centrical vice with pneumatic clamping force
	Machine body with flow coolant system and machine outside cover CE and UVV confirmity
	Complete electric and pneumatic control included
How to work?	Put part into centrical vice and push button
	Automatic procedure: - Part clamping
	- Run forward and make tap

- Head automatical opened at the end and fast retract
- Unclamp part
- Manual unload and load

Hagen & Goebel Werkzeugmaschinen GmbH

 Saelzerweg 3, D - 59494 Soest
 Postbox 1444, D - 59474 Soest

 Telefon +49- (0) 29 21 / 5 90 16 - 0
 Telefax +49- (0) 29 21 / 5 90 16 - 66

 homepage www.hagengoebel.com
 e-mail kontakt@hagengoebel.de